

ADDENDUM TO LEESON SPEEDMASTER USER'S MANUAL (250-0218 REVISION 4)

Figure 11 on Page 21 in this User's Manual was misprinted. Please refer to the diagram in this addendum for the NEMA 1 Mounting Hole Locations.

• **Minarik Corporation** •

901 East Thompson Avenue • Glendale, CA 91201-2011
 Phone: (800) MINARIK (646-2745) • Fax: (800) 394-6334
 Document Number: 250-0218A • Revision 0
 Printed in the U.S.A. - 3/02

Copyright © 2002 by Minarik Corporation - All rights reserved. No part of this document may be reproduced or transmitted in any form without written permission from Minarik Corporation. The information and technical data in this document are subject to change without notice. Minarik Corporation and its Divisions make no warranty of any kind with respect to this material, including, but not limited to, the implied warranties of its merchantability and fitness for a given purpose. Minarik Corporation and its Divisions assume no responsibility for any errors that may appear in this document and make no commitment to update or to keep current the information.




Figure 11. NEMA 1 Mounting Hole Locations